

# UNIT ASSESSMENT REPORT (UAR)



Customer: **Lennox NAS**

Store Name: **Game Stop**

Store ID: **0067**

Property ID: **None**

Address: **9350 S. Cimarron Road Unit 4105**

State: **OK**      ZIP: **74444**

Work Order: **ccb001**      Crew Name: **001 (Name)**

Date Received: **Thursday July 7, 2011**

**Store Comments**

---



Store Front

## Requirements

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Clean Condenser Coils  | <input checked="" type="checkbox"/> Use Chemicals       |
| <input checked="" type="checkbox"/> Split Coils            | <input checked="" type="checkbox"/> Use Pressure        |
| <input checked="" type="checkbox"/> Clean Evaporator Coils | <input checked="" type="checkbox"/> Use Heat            |
| <input checked="" type="checkbox"/> Clean Defusers         | <input checked="" type="checkbox"/> Other Requirements: |
| <input type="checkbox"/> Work Order                        | _____   |
| <input type="checkbox"/> Need Signed Work Order            | _____   |
| <input type="checkbox"/> Need Dated Work Order             | _____   |

Summary	RTUs	Coolers	Freezers	Condenser Coils	Evaporator Coils
# of Units Cleaned	#####	##	##	#####	##
# of Filters Installed	##	####	#####	##	###

## Signature

Customer \_\_\_\_\_ Date \_\_\_\_\_

# UNIT ASSESSMENT REPORT (UAR)



Type:	None
Make:	Aaon
Model Number:	0700abc
Serial number:	Uejdnxidndmxkd
Split Coils:	Single Coil, No Split

Location:	Roof of Store
Condition:	Good
Hail Guards:	No

Compressors - Make/Model	Serial Number	Condition
Copeland Ajdndkxk	Jsuejwbsx	Excellent


Filters - Count	Size	Condition
4	20X20X2 Panel	Clean

Belts - Count	Size	Condition
1	B-48	Fair

## Before Photos



## After Photos



## Comments

---

---

---

---